



User: Rene Hinojosa

Date: 4/8/2022 09:00:02

Round Sling Inspection

Asset Number	72158SS-RS129	Serial Number	
Model Number:		Part Number:	
Owner:	NORDEX	Location:	Site
Description:	ENR10 X 3m ROUND SLING WLL: 15T	Manufacturer:	
		Tags:	Lifting (Shared) Round Sling

Order Number:		Customer PO Number:	
Date:	4/8/2022	Performed By:	Rene Hinojosa
		Form Result:	Pass

Asset Attributes

Form Results

Round Sling Inspection		
Legible Sling ID Tag	Pass	
Acid or Caustic Burns	Pass	
Melting or Charring	Pass	
Holes, Tears, Cuts or Snags	Pass	
Broken or Worn Stitching	Pass	
Excessive Abrasive Wear	Pass	
Knots	Pass	
UV/Sun/Water/Age Damage	Pass	
Load Test Information		
Load Test Performed?	Pass	
Load Pressure		
Load Time		
Load Test Results	Pass	
Inspection Summary		
Comments		





User: Rene Hinojosa

Date: 4/8/2022 09:00:02

Round Sling Inspection

Asset Number	72158SS-RS092	Serial Number	
Model Number:		Part Number:	
Owner:	NORDEX	Location:	Site
Description:	ENR12 X 3.65m ROUND SLING WLL: 30T	Manufacturer:	
		Tags:	Lifting (Shared) Round Sling
Order Number:		Customer PO Number:	
Date:	4/8/2022	Performed By:	Rene Hinojosa
		Form Result:	Pass

Asset Attributes

Form Results

Round Sling Inspection		
Legible Sling ID Tag	Pass	
Acid or Caustic Burns	Pass	
Melting or Charring	Pass	
Holes, Tears, Cuts or Snags	Pass	
Broken or Worn Stitching	Pass	
Excessive Abrasive Wear	Pass	
Knots	Pass	
UV/Sun/Water/Age Damage	Pass	
Load Test Information		
Load Test Performed?	Pass	
Load Pressure		
Load Time		
Load Test Results	Pass	
Inspection Summary		
Comments		





User: Rene Hinojosa

Date: 4/8/2022 09:00:02

Round Sling Inspection

Asset Number	72158SS-RS010	Serial Number	
Model Number:		Part Number:	
Owner:	NORDEX	Location:	Site
Description:	ENR13 X 4M ROUND SLING WLL: 40T	Manufacturer:	
		Tags:	Lifting (Shared) Round Sling

Order Number:		Customer PO Number:	
Date:	4/8/2022	Performed By:	Rene Hinojosa
		Form Result:	Pass

Asset Attributes

Form Results

Round Sling Inspection		
Legible Sling ID Tag	Pass	
Acid or Caustic Burns	Pass	
Melting or Charring	Pass	
Holes, Tears, Cuts or Snags	Pass	
Broken or Worn Stitching	Pass	
Excessive Abrasive Wear	Pass	
Knots	Pass	
UV/Sun/Water/Age Damage	Pass	
Load Test Information		
Load Test Performed?	Pass	
Load Pressure		
Load Time		
Load Test Results	Pass	
Inspection Summary		
Comments		





User: Rene Hinojosa

Date: 4/8/2022 09:00:02

Round Sling Inspection

Asset Number	72158SS-RS080	Serial Number	
Model Number:		Part Number:	
Owner:	NORDEX	Location:	Site
Description:	ENR13 X 3.9m ROUND SLING WLL: 40T	Manufacturer:	
		Tags:	Lifting (Shared) Round Sling

Order Number:		Customer PO Number:	
Date:	4/8/2022	Performed By:	Rene Hinojosa
		Form Result:	Pass

Asset Attributes

Form Results

Round Sling Inspection		
Legible Sling ID Tag	Pass	
Acid or Caustic Burns	Pass	
Melting or Charring	Pass	
Holes, Tears, Cuts or Snags	Pass	
Broken or Worn Stitching	Pass	
Excessive Abrasive Wear	Pass	
Knots	Pass	
UV/Sun/Water/Age Damage	Pass	
Load Test Information		
Load Test Performed?	Pass	
Load Pressure		
Load Time		
Load Test Results	Pass	
Inspection Summary		
Comments		

